



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
RUSTLINGS ROAD	o/s park opp 37	TR: Felling (Armillaria)	Poor physiological condition, crown dieback consistent with Armillaria mellea infection	<i>Acer pseudoplatanus</i>	Replant in same position as previous tree	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	o/s park nr crossing	TR: Felling	Stem in carriageway at 1.5m only, previously struck; obstruction.	<i>Alnus glutinosa</i>	Plant <i>Tilia</i> in existing pit, same place.	<i>Tilia cordata X mongolica 'Hartmann'</i>
RUSTLINGS ROAD	o/s 203	TR: Felling	Kerbs pushed out alignment by buttress root directly behind	<i>Tilia x europea</i>	Plant in same pit	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	o/s 175	TR: Felling	Kerbs broken - cannot replace due to buttress roots in way	<i>Tilia x europea</i>	Plant in new 800 pit in same place	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	o/s 155	TR: Felling	F/W uplifted and kerbs tipped - cannot repair, roots in way	<i>Tilia x europea</i>	Plant in new 800 pit in same place	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	o/s 125	TR: Felling	Kerbs missing, cannot replace without significant root damage	<i>Tilia x europea</i>	Plant in new 800 pit in same place	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	Adj junction Eccy Rd, by bus stop at end road	TR: Felling-	Extensive f/w uplift and kerb displacement	<i>Tilia x europea</i>	Plant in same position in new 800 pit	<i>Tilia cordata 'Rancho'</i>
RUSTLINGS ROAD	opp 25	TR: Felling-	Large buttress root in f/w above tarmac - will be severed upon reconstruction	<i>Tilia x europea</i>	Plant in verge in same position	<i>Tilia cordata 'Rancho'</i>